

PUMP CARTRIDGE REPLACEMENT VALVE

FOR THE FOLLOWING PUMPS:

DV-85N, DV142N, DV200N-DV285N, DV-3E, DV-4E and DV-6E CFM Serial Numbers 0107 and Up

- 1. Remove Cover and Splash Guard.
- 2. Wipe Inside cover surfaces and cartridge clean.
- 3. Use 5/32" Allen wrench for socket headscrews

Note: Do not disturb carteidge assembly bolts or setting screws.

